

Crystal Machine Utility Configuration Guide

1. Open up the Device Manager
 - a. Open the Control Panel
 - b. Choose the Hardware and Sound Category
 - c. Under Devices and Printers choose the Device Manager
2. Check the COM Port machine is connected to
 - a. Found under "Ports"
3. Download the Machine Integration Utility:
 - a. In Crystal, click on Support → Download Support Files → Machine Integration Utility
4. Browse to the Crystal PM folder located in C:\Program Files (x86)\CrystalPM (or C:\Program Files\CrystalPM)
5. Scroll down to the CrystalMachineIntegration.exe application
6. Send a shortcut of the CrystalMachineIntegration.exe application to the desktop
 - a. Right click on the CrystalMachineIntegration application
 - b. Choose Send To
 - c. Click Desktop (create shortcut)
7. Place a copy of the Machine Integration Utility (Shortcut) into the Startup folder
 - a. Open the Run Window by pressing the Windows key on your keyboard and the letter R (⊞ + R)
 - b. Type in Shell:Startup
 - c. Copy the CrystalMachineIntegration –Shortcut on the desktop to this folder
8. Set Up the machine

